

*HMS, Inc.*  
HAZARD MANAGEMENT SERVICES, INC.

PO Box 576848  
Modesto, CA 95357-6848  
(209) 551-2000 • (209) 575-5657 Fax

---

March 4, 2009

Stan Dobbs, Interim Bond Director  
Solano County Community College  
4000 Suisun Valley Road  
Fairfield, CA 94534

Dear Mr. Dobbs,

This letter contains a report on an asbestos sampling exercise conducted by Hazard Management Services, Inc. at the Theater, Building 1200, on your Solano County Community College campus. You requested that we collect a few cursory samples of various building materials to get an idea about abatement implications associated with an upcoming renovation project. Before any renovation can occur a complete and thorough inspection would be necessary.

This inspection was conducted by James E Sharp and Tina Markley, of HMS, Inc. on 2/25/09. A copy of Mr Sharp's Cal/OSHA certification is attached.

Procedures

At your request we collected samples from only the major components of the building. This included wall and ceiling surfaces, flooring, HVAC tape and sealants, baseboards and acoustic ceiling tiles. Plaster and drywall systems were tested on walls and ceilings, the major type of 2' X 4' false ceiling tiles was tested as well as two types of 12" vinyl floor tiles and mastic. Roofing materials were also collected.

A total of only 13 samples was collected and sent to Forensic Analytical Specialties, Inc. for analysis by polarized light microscopy. Forensic is accredited by the National Voluntary Laboratory Accreditation Program for this type of analysis. A copy of it's documentation is attached.

Results

All drywall samples contained asbestos in the skim coat and joint compound. It must be classified as hazardous, asbestos-contained waste. Floor tiles and most of the tile mastic also contained asbestos. Single samples from plaster, one type of 2' X 4' false ceiling panel, brown baseboard and mastic, three roof samples and two duct tape samples all were negative for asbestos.

As noted before this was not a complete inspection. Additional samples will have to be taken to comply with regulatory requirements. There were numerous small quantity items which will require sampling plus the plaster and the roofing will require some confirmation samples.

Page 2

Stan Dobbs, Interim Bond Director  
Solano County Community College

I did not quantify materials during this evaluation due to its cursory nature. Therefore, I cannot give an estimate of abatement costs. However, if all the drywall and flooring is asbestos-containing, and it probably is, abatement costs will easily exceed \$150,000. Of course, if less than all the drywall must be removed costs would be less.


You should also advise all personnel in this building about the drywall and the vinyl floor tile results. Moving the heavy equipment and stage props have damaged some sections of drywall producing some friable materials. Water damage, particularly in the Green Room area, also has produced damaged areas of drywall. It is important to avoid further contact or water problems.

Comments

1. The area shown in picture No. 1 shows water damage to the plaster ceiling in the seating area of the Auditorium. One small piece has already fallen and the plaster was wet from recent rains at the time of our visit. While this plaster does not contain asbestos, the potential for further deterioration increases with each rain storm.
2. The ceiling tiles and the walls above and below the ceiling tiles in the Green Room show damage and mold growth. See picture Nos. 4 and 5. While the saturated ceiling tile may fall the walls are water damaged but are intact.

If you have any questions please call (209) 551-2000.


Sincerely,



James E Sharp  
Cal/OSHA 05-3819

BUILDING 1200  
PICTURES LOG

1. Water damage on plaster ceiling in auditorium seating area
- 2/3. Water damaged drywall next to upstairs Control Room
4. Water damaged ceiling tiles and drywall in Green Room next to stage.
5. Mold growth on walls above water damaged tiles in Green Room.




NO. 1



NO. 2



NO. 3



No. 4



No. 2



# Bulk Asbestos Analysis

(EPA Method 600/R-93-116, Visual Area Estimation)

Hazard Mgmt Services - Modesto  
 Jim Sharp  
 PO Box 576848

Modesto, CA 95357-6848

Client ID: 1146  
 Report Number: B121897  
 Date Received: 02/27/09  
 Date Analyzed: 03/02/09  
 Date Printed: 03/02/09  
 First Reported: 03/02/09

Job ID/Site: M09-024 - Bldg 1200, Solano County Comm. College

Date(s) Collected: 02/26/2009

FASI Job ID: 1146

Total Samples Submitted: 13

Total Samples Analyzed: 13

Sample ID	Lab Number	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer
HMS-M09-024-1	10844625						
Layer: White Drywall			ND				
Layer: Off-White Skimcoat/Joint Compound		Chrysotile	2 %				
Layer: Paint			ND				
Total Composite Values of Fibrous Components:		Asbestos (Trace)					
Cellulose (20 %) Fibrous Glass (10 %)							
HMS-M09-024-2	10844626						
Layer: White Drywall			ND				
Layer: Off-White Skimcoat/Joint Compound		Chrysotile	2 %				
Layer: Paint			ND				
Total Composite Values of Fibrous Components:		Asbestos (Trace)					
Cellulose (20 %) Fibrous Glass (10 %)							
HMS-M09-024-3	10844627						
Layer: White Drywall			ND				
Layer: Off-White Skimcoat/Joint Compound		Chrysotile	2 %				
Layer: Paint			ND				
Total Composite Values of Fibrous Components:		Asbestos (Trace)					
Cellulose (20 %) Fibrous Glass (10 %)							
HMS-M09-024-4	10844628						
Layer: White Tape			ND				
Total Composite Values of Fibrous Components:		Asbestos (ND)					
Cellulose (90 %)							
HMS-M09-024-5	10844629						
Layer: White Tape			ND				
Total Composite Values of Fibrous Components:		Asbestos (ND)					
Cellulose (90 %)							
HMS-M09-024-6	10844630						
Layer: White Plaster			ND				
Total Composite Values of Fibrous Components:		Asbestos (ND)					
Cellulose (Trace)							

Client Name: Hazard Mgmt Services - Modesto

Report Number: B121897

Date Printed: 03/02/09

Sample ID	Lab Number	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer
HMS-M09-024-7	10844631						
Layer: Beige Fibrous Material							ND
Layer: Paint							ND
Total Composite Values of Fibrous Components:		Asbestos (ND)					
Cellulose (35%)	Fibrous Glass (45%)						
HMS-M09-024-8	10844632						
Layer: Beige Tile		Chrysotile	2 %				
Layer: Black Mastic		Chrysotile	5 %				
Total Composite Values of Fibrous Components:		Asbestos (2%)					
Cellulose (Trace)							
HMS-M09-024-9	10844633						
Layer: Beige Tile		Chrysotile	2 %				
Layer: Yellow Mastic							ND
Total Composite Values of Fibrous Components:		Asbestos (2%)					
Cellulose (Trace)							
HMS-M09-024-10	10844634						
Layer: Brown Non-Fibrous Material							ND
Layer: Brown Mastic							ND
Total Composite Values of Fibrous Components:		Asbestos (ND)					
Cellulose (Trace)							
HMS-M09-024-11	10844635						
Layer: Stones							ND
Layer: Black Tar							ND
Layer: Black Felt							ND
Total Composite Values of Fibrous Components:		Asbestos (ND)					
Fibrous Glass (45%)							
HMS-M09-024-12	10844636						
Layer: Black Semi-Fibrous Tar							ND
Total Composite Values of Fibrous Components:		Asbestos (ND)					
Cellulose (20%)	Synthetic (10%)						
HMS-M09-024-13	10844637						
Layer: Black Tar							ND
Total Composite Values of Fibrous Components:		Asbestos (ND)					
Cellulose (Trace)							

James Flores, Laboratory Supervisor, Hayward Laboratory

Note: Limit of Quantification ('LOQ') = 1%. 'Trace' denotes the presence of asbestos below the LOQ. 'ND' = 'None Detected'.

Analytical results and reports are generated by Forensic Analytical at the request of and for the exclusive use of the person or entity (client) named on such report. Results, reports or copies of same will not be released by Forensic Analytical to any third party without prior written request from client. This report applies only to the sample(s) tested. Supporting laboratory documentation is available upon request. This report must not be reproduced except in full, unless approved by Forensic Analytical. The client is solely responsible for the use and interpretation of test results and reports requested from Forensic Analytical. This report must not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. Government. Forensic Analytical is not able to assess the degree of hazard resulting from materials analyzed. Forensic Analytical reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified. All samples were received in acceptable condition unless otherwise noted.

# HAZARD MANAGEMENT SERVICES, INC.

## BULK Material Analysis Request Form

P.O. BOX 576848  
 MODESTO, CA 95357-6848  
 (209) 551-2000  
 FAX (209) 575-5657

Date: 2-26-09

HMS Contact: JIM SHARP

Special Instructions: Please fax results to 209-575-5657

Analysis Requested:

PLM with Dispersion Staining  
 \_\_\_ 2 Hr; \_\_\_ 24 Hr;  48 Hr; \_\_\_ Extended

Collected by: JIM SHARP

TEM Water (5 Day)

Date collected: 2-25-09

TEM Bulk (5 Day)

Client: Solano County Comm. College

Job Site/Project: BLDG. 1200

Laboratory: Forensic

Job No.: MO9-024

Sample #	Results %	Material Description/Location
HMS-MO9-024-01		DW - FIELD
		PERIMETER WALL - GREEN RM - BLDG 1200
02		DW 2 JOINT COMPOUND
		THEATER - BLDG 1200
03		DW FIELD
		CONTROL RM - BLDG 1200
04		DUCT TAPE & SEALANT
		STAGE CATWALK <del>WITH SEALANT</del> BLDG 1200
05		DUCT TAPE WITH SEALANT
		CONTROL RM VENT DUCTS - BLDG 1200
06		CEILING PLASTER
		MAIN AUDITORIUM - BLDG 1200
07		2x4 KLP
		GREEN RM CEILING - WET AREA
08		VFT + MASTIC
		CONTROL RM STORAGE
09		VFT + MASTIC
		STAGE AREA - BLDG 1200
10		BROWN BASEBOARD + MASTIC
		CONTROL RM STORAGE
11		LAP FOR ROOFING
		BLDG 1200
12		PENETRATION MASTIC
		ROOF - BLDG 1200
13		ROOF MASTIC
		BLDG 1200

CS Form 12/01/08 BULK.MAL.rpt. 12-7/08

2/27/09 ETC 1020am THANKS - J Sharp



# Hazard Management Services, Inc.

*This is to confirm that*

**James E Sharp**

*has attended the eight-hour*

**AHERA Refresher Course for Asbestos Contractors and Supervisors**  
*and has completed the requisite training for asbestos accreditation under TSCA Title II*  
**May 13, 2008**

Certificate number: HMSCSR07

Valid until: May 13, 2009

Cal/OSHA approval number: CA-025-04

*Michael C Sharp*

Michael C Sharp  
CAC, DHS, I/S/M, MCSE NT 4.0+I  
AHERA Training Director  
Hazard Management Services, Inc.

# Hazard Management Services, Inc.

*This is to confirm that*

**James E Sharp**

*has attended the four-hour*

*AHERA Refresher Course for Asbestos Inspectors*

*and has completed the requisite training for asbestos accreditation under TSCA Title II*

**January 28, 2008**

Certificate number: 58

Valid until: January 28, 2009

Cal/OSHA approval number: CA-025-06



Michael C. Sharp  
CAC, DHS I/S/M, MCSE NT 4.0+I  
AHERA Training Director  
Hazard Management Services, Inc.

DEPARTMENT OF INDUSTRIAL RELATIONS  
**DIVISION OF OCCUPATIONAL SAFETY AND HEALTH**  
**ASBESTOS CONSULTANT and TRAINER APPROVAL UNIT**

2211 Park Towne Circle, Suite 1  
 Sacramento, CA 95825

Tel: (916) 574-2993 Fax: (916) 483-0572



506013819T

279

Hazard Management Services  
 James E Sharp  
 P. O. Box 576848  
 Modesto

May 28, 2008

CA 95357-6848

Dear Certified Asbestos Consultant or Technician:

Enclosed is your certification card. **To maintain your certification, please abide by the rules printed on the back of the certification card.**

Your certification is valid for a period of one year. If you wish to renew your certification, you must apply for renewal at least 60 days before the expiration date shown on your card. [8 CCR 341.15(h)(1)].

Please hold and do not send copies of your required AHERA refresher renewal certificates to our office until you apply for renewal of your certification. Certificates must be kept current if you are actively working as a CAC or CSST. The grace period is only for those who are not actively working as a CAC or CSST.

Please inform our office at the above address, fax number or [actu@dir.ca.gov](mailto:actu@dir.ca.gov) of any changes in your contact/ mailing information within 15 days of the change.

Sincerely,

Jeff Ferrell  
 Senior Industrial Hygienist

JF/ms

Attachment: Certification Card  
 cc: File

(Renewal - Card Attached Revised 8/29/05)

State of California  
 Division of Occupational Safety and Health  
 Certified Site Surveillance Technician

James E Sharp

Name

Certification No. 05-3819

Expires on 06/16/09



This certification was issued by the Division of Occupational Safety and Health as authorized by Sections 7180 et seq. of the Business and Professions Code.



SCOPE OF ACCREDITATION TO ISO/IEC 17025:2005

Forensic Analytical Laboratories, Inc.
3777 Depot Road, Suite 409
Hayward, CA 94545-2761
Mr. David Sandusky
Phone: 510-887-8828 Fax: 510-887-4218
E-Mail: Daves@forensica.com
URL: http://www.forensica.com

BULK ASBESTOS FIBER ANALYSIS (PLM)

NVLAP LAB CODE 101459-0

NVLAP Code Designation / Description

18/A01 EPA-600/M4-82-020: Interim Method for the Determination of Asbestos in Bulk Insulation Samples

2008-07-01 through 2009-06-30

Effective dates

Sally S. Bruce

For the National Institute of Standards and Technology