

SERVICES

Worker Health and Safety

OSHA Training and Compliance

Safety Audits

Ergonomics

IIPP and Specialized Programs

Hazard Communication

Fleet Safety

Indoor Air Quality

Mold Consulting

Moisture Management Plans

Industrial Hygiene

Asbestos and Lead Management

Hazardous Materials

Environmental Site Assessments
Phase I,II III

Risk Management

Subsurface Investigation

Litigation Support

Hazardous Materials Survey Report (revised)

Solano Community College
4000 Suisun Valley Road
Building 1100 Portables
Fairfield, CA

RGA Project No: SCC32836

August 8, 2013

Prepared for:

c/o John Lett with Kitchell
Solano Community College
4000 Suisun Valley Road, building 1900
Fairfield, CA

Prepared by:

RGA Environmental, Inc.
1466 66th Street
Emeryville, CA 94608

Report prepared by:  Michael Bishop
Senior Industrial Hygienist, CAC 07-4275

Report reviewed by:  Tedd Kattchee
Project Manager, CAC 99-2557

TABLE OF CONTENTS

1. EXECUTIVE SUMMARY1

2. SCOPE OF WORK1

3. METHODS AND SAMPLING STRATEGY2

4. ASBESTOS RESULTS3

5. LEAD RESULTS5

7. CONCLUSIONS AND RECOMMENDATIONS.....5

8. REGULATORY REQUIREMENTS.....6

9. LIMITATIONS.....7

APPENDICES

- 1. Laboratory Results and Chain of Custody – Asbestos**
- 2. Laboratory Results and Chain of Custody – Lead**
- 3. Sample & Material Location Diagram**
- 4. Inspector Certificates**

Hazardous Materials Survey Report

*Building 1100
Solano Community College District
4000 Suisun Valley Road
Fairfield, California*

1. Executive Summary

The following is a report of the pre-demolition asbestos and lead survey conducted by Tedd Kattchee, Certified Asbestos Consultant (CAC) with RGA Environmental, Inc. (RGA). The survey was performed on May 7, 2013 in addition to samples collected on May 26, 2011 at Solano Community College in Building 1100 located at 4000 Suisun Valley Road in Fairfield, California. RGA returned to the site on August 2, 2013 to conduct additional sampling.

The survey area included the interior, exterior, and roofing materials of approximately 4,000 square foot of five portable buildings attached or adjacent to one other. The finish roof is a rolled asphalt composite system. The portables are scheduled to be removed later in the year.

A total of twenty-six (26) homogenous suspected asbestos containing materials (ACMs) were identified throughout the interior and exterior of the structure. Four (4) of the materials sampled were determined to be positive for asbestos content.

Two (2) painted surfaces were sampled for potential lead content. Two (2) of the materials sampled were reported above the laboratory detection limit for lead.

Mercury containing fluorescent light tubes were present throughout the interior of the building. No mercury switches were observed in the building.

Modular HVAC units on the side of the portables indicate the presence of refrigerants

2. Scope of Work

The scope of the survey was as follows:

- Inspect the subject property for the presence of suspect ACMs, lead-containing paint, mercury containing products, potential polychlorinated biphenyls (PCBs) containing materials, and chlorofluorocarbon (CFC) containing equipment.
- Collect samples of suspect ACMs following a National Emissions Standards for Hazardous

Air Pollutants (NESHAPS) protocol for sample collection for a renovation survey.

- Asbestos bulk samples will be analyzed using polarized light microscopy (PLM) in accordance with the EPA's July 1993 method for the determination of asbestos in bulk building materials - EPA 600/R-93/116.
- Collect bulk paint chip samples of primary painted surfaces and other materials suspected to be lead containing. Bulk samples will be analyzed at an accredited laboratory by Flame Atomic Absorption (AA) for Total Lead reported in parts per million (ppm).
- Submit written report including analytical results, regulatory requirements and conclusions.

3. Methods and Sampling Strategy

Visual Inspection

Accessible building materials on the interior and exterior of the structure was visually inspected using the methods presented in the federal Asbestos Hazard Emergency Response Act (AHERA) regulations (40 CFR, Part 763) as a guideline. AHERA was originally only applicable to schools, however State and Federal Occupational Safety and Health Administration (OSHA) and Asbestos School Hazard Abatement Reauthorization Act (ASHARA) have adopted the AHERA sampling methodology for all buildings subject to demolition or renovation.

Visual Inspection for Mercury Containing Materials

Approximately fifty (50) fluorescent light tubes (mercury containing) were identified throughout the building. All of the light tubes should be handled without breakage prior to removal of fixtures. RGA did not observe any mercury switches in the building.

Visual Inspection for PCB-containing Equipment

Approximately 230 fluorescent light ballasts were identified inside the structure. RGA observed "No PCBs" labels on the ballasts inspected. All ballasts should be inspected prior to disposal to verify the presence/absence of PCBs. Ballasts should be assumed to be PCB-containing unless specified by the manufacturer's label as containing "No PCBs".

Visual Inspection for CFC Containing Equipment

RGA visually inspected for potential CFC containing equipment. Six (6) wall-mounted HVAC units were observed. There were indications that the equipment likely contains R-22 refrigerant, which is scheduled for phase-out by the EPA under the Montreal Protocol. No testing was performed. All refrigerant systems should be verified prior to disconnection; lubricating fluids and refrigerant must be reclaimed for recycling or destruction prior to removal of the equipment.

Bulk Sampling of Asbestos

Bulk samples were collected of homogeneous suspect ACM on the subject property. A homogeneous material is defined as a surfacing material, thermal system insulation, or

miscellaneous material that is uniform in color, texture and age of construction. Examples of homogeneous materials include:

- Pipe-insulation produced by the same manufacturer and installed during the same time period;
- Resilient flooring of identical color and pattern;
- Troweled on surfacing materials located in contiguous areas.

The survey area was visually inspected for the presence of suspect materials. As materials were identified, bulk samples were obtained with the aid of a coring device or other hand tool and placed into individual sampling bags. Each sample was given a discreet identification number and recorded on field notes as well as chain-of-custody forms. Refer to accompanying tables and appendices for details on material sample locations and results.

Bulk Sample Analysis - Asbestos

Bulk samples were analyzed by RGA in Seattle, Washington. RGA is accredited under the National Institute of Standards and Technology's National Voluntary Laboratory Accreditation Program (NVLAP).

When None Detected (ND) appears in this report, it should be interpreted as meaning no asbestos was observed in the sample material above the reliable limit of detection for the PLM method.

Note: Under EPA assessment criteria, if a single sample of a homogeneous material test positive for asbestos, all areas of that homogeneous material are considered to be asbestos containing.

Bulk Sampling of Lead Paint

Paint chip and bulk samples were collected using a hand scraper or chisel and were placed into individual plastic sampling containers. Each sample was provided a discreet sample number, which was recorded on a chain-of-custody form. The samples were transported under chain-of-custody procedures to RGA in Seattle, Washington. Please refer to Table III for details

on sample locations and sample results. All paint and ceramic tile glazing samples were analyzed for lead content using the Flame Atomic Absorption spectroscopy in accordance to EPA Method SW846-7420.

4. Asbestos Results

During the survey, twenty-six (26) suspect homogeneous materials were identified at the subject property. Four (4) of these materials were reported as positive for asbestos content. The confirmed asbestos containing materials are listed in Table I below.

**TABLE I
 ASBESTOS-CONTAINING MATERIALS**

Material Description	Material Location	Approx. Quantity	Asbestos Type
Gray Penetration Mastic	Throughout Roofing Field All Portables	40 sq. ft.	5% CH
Drywall with Joint Compound	Room 1102 and 1107	2,200 sq. ft.	Drywall: ND Joint Compound: Pt CT 0.25% Comp <1% CH
12" Vinyl Floor Tile with Yellow Mastic – Beige	Room 1101	1,200 sq. ft.	VFT: 3% CH Mastic: ND
12" Floor Tile Under Carpets – Off-White	Room 1109	1,300 sq. ft.	Floor Tile: 4% CH Yellow Mastic: ND Black Mastic: ND

NA = Not Applicable, CH = Chrysotile, Pt Ct = Point Count by PLM. RACM = Regulated asbestos containing material (friable), Cat. I = Non-friable (note ACM must be reclassified as a RACM if rendered friable during removal), Cat. II = Category II Non-friable (note ACM must be reclassified as a RACM if rendered friable during removal)

Fifteen (15) suspect materials were sampled and found to be negative for asbestos content. The non-asbestos containing materials are listed in Table II below.

**TABLE II
 NON-ASBESTOS CONTAINING MATERIALS**

Material Description	Material Location(s)
Sheet Vinyl Flooring Blue	1103 -1107
Sheet Vinyl Flooring Beige	1107 Bathrooms
Fiberboard wall panels	Throughout Portables
Wall cover White	1105
1' ceiling tile (no mastic)	Throughout Portables
Wall Panel Mastic - Brown	Throughout Portables*
Exterior tan paint	Exterior all portables
Rolled Roofing Field (Old and New)	All Portables Roof
HVAC Vibration dampener	Roof 1106
Residual Black Mastic	1106*
2' x 4' Ceiling Tiles –Fissure – White	1106
Brown Exterior paint	Exterior
Drywall with Joint Compound	1109
Wall Texture	Throughout
4" Gray Cove Base with Beige Mastic	Room 1109
4" Brown Cove Base with Beige Mastic	Room 1109 Restroom
12" Gray and Tan Multi-color Floor Tile – 2 Layers with Black Mastic	Room 1109 Restroom
White Carpet Mastic	Main Office Center
Fiberboard Walls with Joint Compound	Perimeter Walls

*=collected on 5/26/11

5. Lead Results

Samples of two (2) painted surfaces were collected from the survey area. Both of the materials sampled were reported above laboratory detection limits for lead. Table III below summarizes the sampling locations and results for the materials.

**TABLE III
LEAD IN PAINT SAMPLE RESULTS**

Sample Number	Material Description and Location	Results mg/kg (ppm)
Pb-1	Tan Exterior Body Paint	4,440
Pb-2	Brown Exterior Trim Paint	3,360

Mg/kg= Milligram per kilogram, ppm = parts per million

7. Conclusions and Recommendations

Based upon the scope of the work, RGA concludes the following:

- Asbestos was detected in four (4) materials: wallboard joint compound, roofing mastics and floor tiles. These materials should be removed by a licensed and registered asbestos abatement contractor if materials disturbed will exceed 100 square feet. All workers shall be properly trained for asbestos removal work.
- Lead was detected above the laboratory detection limit in two (2) of the materials tested within the survey area. None of these samples exceed 5000ppm the level at which the paint is considered lead.
- Mercury-containing fluorescent-light tubes were identified throughout the survey area. Mercury-containing tubes and bulbs should be removed from the fixtures or equipment without breakage and packaged for mercury reclamation as a universal waste through an appropriate vendor prior to removal of any fixtures.
- Suspect PCB-containing ballasts associated with the fluorescent lights were observed throughout the vacant space. All of the ballasts inspected during the survey were labeled as "No PCBs". Each ballast label should be inspected for the phrase "No PCBs" prior to disposal. Ballasts not labeled as such should be assumed to contain PCBs. PCB ballasts should be removed from fixtures and disposed of as PCB-containing materials prior to disposal of the fixtures

- One (2) HVAC units was observed on the roof of the building. Six (6) smaller units mounted on the side of the portables likely utilize R-22 refrigerant. All refrigerant systems should be verified prior to disconnection; lubricating fluids and refrigerant must be reclaimed for recycling or destruction prior to removal of the equipment.
- No tritium gas exit signs were observed in the portables.

8. Regulatory Requirements

Asbestos

Asbestos-containing materials are present in the building in concentrations greater than one tenth of one percent (0.1%). Impacting materials containing greater than 0.1% asbestos either through repair, maintenance, or demolition activities triggers numerous regulations enforced by such agencies as OSHA (worker protection) and EPA (environmental exposure, transportation and disposal).

Listed below are the regulations that apply if the materials are removed:

- Any individual who contracts to provide health and safety services relating to ACMs must be certified by Cal-OSHA as either a Certified Asbestos Consultant or a Site Surveillance Technician. The activities they are certified to provide include: conducting asbestos surveys; writing work plans or specifications for abatement; monitoring the work of abatement contractors; collecting air samples; and determining if the work area is safe for re-occupancy by non-asbestos workers. Regulation: Cal-OSHA 8 CCR 1529 (q)(1).
- If more than 100 square feet of materials that contain greater than 0.1% asbestos will be abated, they must be abated by a Cal-OSHA registered asbestos abatement contractor. Regulation: Cal-OSHA 8 CCR 1529 (R).
- An ACM that is classified by OSHA as other/miscellaneous materials have been assumed present. Removal of these materials is considered a Class II activity according to Cal-OSHA regulations. Work practices and engineering controls for Class II work are specified in Cal-OSHA 8 CCR 1529 (g) (7-8).
- If more than 160 square feet or 260 linear feet of friable ACM (RACM) will likely be removed, the abatement contractor must notify the Bay Area Air Quality Management District (BAAQMD) ten (10) days prior to removing the material. Regulation: BAAQMD Rule 11.

Lead

Painted interior surfaces observed during the survey were all intact. Limited loose and peeling paint was observed on the exterior of the portables. Impacting lead or lead-containing paint either through repair, maintenance, renovation or demolition activities triggers numerous regulations enforced by such agencies as OSHA (worker protection), EPA (environmental exposure, transportation and disposal), and Department of Public Health

(DPH).

Listed below are the lead paint regulations that apply if the paint is removed:

- There are presently no federal, state or local regulations limiting the concentration of lead in public sector buildings, however several regulations established for the private sector as well as for government subsidized housing are used industry wide as guidelines for assessing exposure to lead. The Consumer Product Safety Commission (CPSC) has set a maximum limit of 600 ppm in paint used for residential purposes. The Department of Housing and Urban Development (HUD) requires abatement of lead hazards involving paint in concentrations exceeding 5,000 ppm.
- Disposal of all lead-containing paint is regulated at concentrations at or exceeding 1,000 ppm as stated in 40 Code of Federal Regulations (CFR) Part 263 - Land Disposal Regulations and Title 22, Division 4 Environmental Health of the California Administrative Code: Lead containing materials that exceed 50 ppm must be additionally analyzed to determine possible waste disposal restrictions with respect to lead. However, lead related work at any lead concentration is regulated under the OSHA statutes.
- Federal OSHA as well as California OSHA regulates all worker exposure during construction activities that impact lead-containing paint. California OSHA enforces the Lead in Construction Standard in Title 8 CCR 1532.1. The scope covers construction work where employees may be exposed to lead during such activities as demolition, removal, surface preparation for re-painting, renovation, clean-up and routine maintenance. The OSHA specified method of compliance includes respiratory protection, protective clothing and equipment, housekeeping, hygiene facilities, medical surveillance, and training, among other requirements.

9. Limitations

RGA Environmental Inc. (RGA) warrants that the findings contained herein have been prepared in general accordance with accepted professional practices as applied by similar professionals in the community at the time of its preparation. Changes in the state of the art or in applicable regulations cannot be anticipated and have not been addressed in this report.

Appendix 1

Laboratory Results and Chain of Custody – Asbestos



1730 Minor Avenue, Suite 900, Seattle, WA 98101
 OFFICE: (206) 281-8858 FAX: (206) 281-8922 email: laboratory@rgaenv.com

Bulk Asbestos Fiber Analysis
 (EPA 600/R-93/116)



NVLAP LAB CODE 200613-0

Solano Community College

Project Location: Bldg 1100
 Solano Community College

RGA Batch Number: **13-1026**

RGA Project Number: **SCC32836**

Number of Samples: **33**

Report Key				
Client Sample ID RGA Lab ID	Layer ID (if applicable) Layer Description Layer Comments (if applicable)	Asbestos Components	Non-Asbestos Fibrous Components	Non-Fibrous Components
1A 13010713	L-1 Linoleum, blue pebble pattern	No Asbestos Detected		75% Plastic Particles 25% Vinyl Filler and Binder
	L-2 Paper backing	No Asbestos Detected	65% Cellulose	25% Filler and Binder 10% Mineral Particles
	L-3 Beige/gray mastic	No Asbestos Detected		90% Resin and Binder 10% Mineral Filler and Binder
1B 13010714	L-1 Linoleum, blue pebble pattern	No Asbestos Detected		75% Plastic Particles 25% Vinyl Filler and Binder
	L-2 Paper backing	No Asbestos Detected	65% Cellulose	25% Filler and Binder 10% Mineral Particles
	L-3 Beige/gray mastic	No Asbestos Detected		90% Resin and Binder 10% Filler and Binder
2A 13010715	L-1 Drywall	No Asbestos Detected	20% Cellulose 10% Glass Fiber	65% Gypsum Filler and Binder 5% Mineral Particles
	L-2 Joint compound	No Asbestos Detected		85% Calcite Filler and Binder 10% Mineral Filler and Binder 5% Paint

This report relates only to the items tested. If samples are not collected by RGA Environmental personnel, accuracy of the results is limited by the methodology and expertise of the sample collector. Analyses are cross-checked with other laboratories for quality assurance purposes. This report shall not be reproduced except in full, without written approval of RGA Environmental. It shall not be used to claim product endorsement by NVLAP or any other agency of the U.S. Government.

Sampled By: Tedd Kattchee
 Received By: Abdulrazzak Mansur 5/10/2013
 Reviewed By: Aruna Turaga 5/13/2013

Analyzed By: William Russell Browne
 Russell Browne 5/13/2013



1730 Minor Avenue, Suite 900, Seattle, WA 98101
 OFFICE: (206) 281-8858 FAX: (206) 281-8922 email: laboratory@rgaenv.com

Bulk Asbestos Fiber Analysis
 (EPA 600/R-93/116)



NVLAP LAB CODE 200613-0

Solano Community College

Project Location: Bldg 1100
 Solano Community College

RGA Batch Number: **13-1026**

RGA Project Number: **SCC32836**

Number of Samples: **33**

Report Key				
Client Sample ID RGA Lab ID	Layer ID (if applicable) Layer Description Layer Comments (if applicable)	Asbestos Components	Non-Asbestos Fibrous Components	Non-Fibrous Components
2B 13010716	L-1 Drywall	No Asbestos Detected	20% Cellulose 10% Glass Fiber	65% Gypsum Filler and Binder 5% Mineral Particles
	L-2 Joint compound	No Asbestos Detected		85% Calcite Filler and Binder 10% Mineral Filler and Binder 5% Paint
2C 13010717	L-1 Drywall	No Asbestos Detected	20% Cellulose 10% Glass Fiber	65% Gypsum Filler and Binder 5% Mineral Particles
	L-2 Joint compound	No Asbestos Detected		85% Calcite Filler and Binder 10% Mineral Filler and Binder 5% Paint
3A 13010718	L-1 Linoleum, beige pebble pattern	No Asbestos Detected		75% Plastic Particles 25% Vinyl Filler and Binder
	L-2 Paper backing	No Asbestos Detected	65% Cellulose	25% Filler and Binder 10% Mineral Particles
	L-3 Beige mastic	No Asbestos Detected		90% Resin and Binder 10% Filler and Binder

This report relates only to the items tested. If samples are not collected by RGA Environmental personnel, accuracy of the results is limited by the methodology and expertise of the sample collector. Analyses are cross-checked with other laboratories for quality assurance purposes. This report shall not be reproduced except in full, without written approval of RGA Environmental. It shall not be used to claim product endorsement by NVLAP or any other agency of the U.S. Government.

Sampled By: Tedd Kattchee
 Received By: Abdulrazzak Mansur 5/10/2013
 Reviewed By: Aruna Turaga 5/13/2013

Analyzed By: William Russell Browne
 Russell Browne 5/13/2013



1730 Minor Avenue, Suite 900, Seattle, WA 98101
 OFFICE: (206) 281-8858 FAX: (206) 281-8922 email: laboratory@rgaenv.com

Bulk Asbestos Fiber Analysis
 (EPA 600/R-93/116)



NVLAP LAB CODE 200613-0

Solano Community College

Project Location: Bldg 1100
 Solano Community College

RGA Batch Number: **13-1026**

RGA Project Number: **SCC32836**

Number of Samples: **33**

Report Key				
Client Sample ID RGA Lab ID	Layer ID (if applicable) Layer Description Layer Comments (if applicable)	Asbestos Components	Non-Asbestos Fibrous Components	Non-Fibrous Components
3B 13010719	L-1 Linoleum, beige pebble pattern	No Asbestos Detected		75% Plastic Particles 25% Vinyl Filler and Binder
	L-2 Paper backing	No Asbestos Detected	65% Cellulose	25% Filler and Binder 10% Mineral Particles
	L-3 Beige mastic	No Asbestos Detected		90% Resin and Binder 10% Filler and Binder
4A 13010720	L-1 4" brown cove base	No Asbestos Detected		90% Rubber Particles 10% Vinyl Filler and Binder
	L-2 White mastic	No Asbestos Detected		90% Resin and Binder 10% Filler and Binder
5A 13010721	L-1 Wall covering white	No Asbestos Detected	75% Cellulose	15% Paint 10% Vinyl Filler and Binder
	L-2 Off-white/beige mastic	No Asbestos Detected		90% Resin and Binder 10% Filler and Binder
5B 13010722	L-1 Wall covering white	No Asbestos Detected	75% Cellulose	15% Paint 10% Vinyl Filler and Binder
	L-2 Off-white/beige mastic	No Asbestos Detected		90% Resin and Binder 10% Filler and Binder

This report relates only to the items tested. If samples are not collected by RGA Environmental personnel, accuracy of the results is limited by the methodology and expertise of the sample collector. Analyses are cross-checked with other laboratories for quality assurance purposes. This report shall not be reproduced except in full, without written approval of RGA Environmental. It shall not be used to claim product endorsement by NVLAP or any other agency of the U.S. Government.

Sampled By: Tedd Kattchee
 Received By: Abdulrazzak Mansur 5/10/2013
 Reviewed By: Aruna Turaga 5/13/2013

Analyzed By: William Russell Browne
 Russell Browne 5/13/2013



1730 Minor Avenue, Suite 900, Seattle, WA 98101
 OFFICE: (206) 281-8858 FAX: (206) 281-8922 email: laboratory@rgaenv.com

Bulk Asbestos Fiber Analysis
 (EPA 600/R-93/116)



NVLAP LAB CODE 200613-0

Solano Community College

Project Location: Bldg 1100
 Solano Community College

RGA Batch Number: **13-1026**

RGA Project Number: **SCC32836**

Number of Samples: **33**

Report Key				
Client Sample ID RGA Lab ID	Layer ID (if applicable) Layer Description Layer Comments (if applicable)	Asbestos Components	Non-Asbestos Fibrous Components	Non-Fibrous Components
2D 13010723	L-1 Drywall	No Asbestos Detected	20% Cellulose 10% Glass Fiber	65% Gypsum Filler and Binder 5% Mineral Particles
	L-2 Joint compound	2% Chrysotile		83% Calcite Filler and Binder 10% Mineral Filler and Binder 5% Paint
Layer Comments: The wall unit, as a whole, contains less than 1% chrysotile asbestos by visual estimate.				
2E 13010724	L-1 Drywall	No Asbestos Detected	20% Cellulose 10% Glass Fiber	65% Gypsum Filler and Binder 5% Mineral Particles
	L-2 Joint compound	No Asbestos Detected		85% Calcite Filler and Binder 10% Mineral Filler and Binder 5% Paint
2F 13010725	L-1 Drywall	No Asbestos Detected	20% Cellulose 10% Glass Fiber	65% Gypsum Filler and Binder 5% Mineral Particles
	L-2 Joint compound	2% Chrysotile		83% Calcite Filler and Binder 10% Mineral Filler and Binder 5% Paint
Layer Comments: The wall unit, as a whole, contains less than 1% chrysotile asbestos by visual estimate.				
6A 13010726	1' ceiling tile, no mastic	No Asbestos Detected	85% Cellulose	10% Resin and Binder 5% Paint
6B 13010727	1' ceiling tile, no mastic	No Asbestos Detected	85% Cellulose	10% Resin and Binder 5% Paint

This report relates only to the items tested. If samples are not collected by RGA Environmental personnel, accuracy of the results is limited by the methodology and expertise of the sample collector. Analyses are cross-checked with other laboratories for quality assurance purposes. This report shall not be reproduced except in full, without written approval of RGA Environmental. It shall not be used to claim product endorsement by NVLAP or any other agency of the U.S. Government.

Sampled By: Tedd Kattchee
 Received By: Abdulrazzak Mansur
 Reviewed By: Aruna Turaga

5/10/2013
 5/13/2013

Analyzed By: William Russell Browne
 Russell Browne
 5/13/2013



1730 Minor Avenue, Suite 900, Seattle, WA 98101
 OFFICE: (206) 281-8858 FAX: (206) 281-8922 email: laboratory@rgaenv.com

Bulk Asbestos Fiber Analysis
 (EPA 600/R-93/116)



NVLAP LAB CODE 200613-0

Solano Community College

Project Location: Bldg 1100
 Solano Community College

RGA Batch Number: **13-1026**

RGA Project Number: **SCC32836**

Number of Samples: **33**

Report Key				
Client Sample ID RGA Lab ID	Layer ID (if applicable) Layer Description Layer Comments (if applicable)	Asbestos Components	Non-Asbestos Fibrous Components	Non-Fibrous Components
6C 13010728	1' ceiling tile, no mastic	No Asbestos Detected	85% Cellulose	10% Resin and Binder 5% Paint
7A 13010729	Exterior brown coating	No Asbestos Detected		75% Paint 15% Calcite Filler and Binder 10% Mineral Filler and Binder
7B 13010730	Exterior brown coating	No Asbestos Detected		75% Paint 15% Calcite Filler and Binder 10% Mineral Filler and Binder
8A 13010731	Gray mastics, roof Layer Comments: First positive stop.	5% Chrysotile Positive Stop		90% Asphalt Filler and Binder 5% Mineral Particles
9A 13010734	Roofing field rolled	No Asbestos Detected	5% Cellulose	45% Asphalt Filler and Binder 30% Rocks 5% Mineral Particles
9B 13010735	Roofing field rolled	No Asbestos Detected	15% Glass Fiber 5% Cellulose	45% Asphalt Filler and Binder 30% Rocks 5% Mineral Particles
9C 13010736	Roofing field rolled	No Asbestos Detected	15% Glass Fiber 5% Cellulose	45% Asphalt Filler and Binder 30% Rocks 5% Mineral Particles
10A 13010737	Fiber wall panel	No Asbestos Detected	55% Cellulose 25% Synthetic	10% Resin and Binder 10% Paint

This report relates only to the items tested. If samples are not collected by RGA Environmental personnel, accuracy of the results is limited by the methodology and expertise of the sample collector. Analyses are cross-checked with other laboratories for quality assurance purposes. This report shall not be reproduced except in full, without written approval of RGA Environmental. It shall not be used to claim product endorsement by NVLAP or any other agency of the U.S. Government.

Sampled By: Tedd Kattchee
 Received By: Abdulrazzak Mansur 5/10/2013
 Reviewed By: Aruna Turaga 5/13/2013

Analyzed By: William Russell Browne
 Russell Browne 5/13/2013



1730 Minor Avenue, Suite 900, Seattle, WA 98101
 OFFICE: (206) 281-8858 FAX: (206) 281-8922 email: laboratory@rgaenv.com

Bulk Asbestos Fiber Analysis
 (EPA 600/R-93/116)



NVLAP LAB CODE 200613-0

Solano Community College

Project Location: Bldg 1100
 Solano Community College

RGA Batch Number: **13-1026**

RGA Project Number: **SCC32836**

Number of Samples: **33**

Report Key				
Client Sample ID RGA Lab ID	Layer ID (if applicable) Layer Description Layer Comments (if applicable)	Asbestos Components	Non-Asbestos Fibrous Components	Non-Fibrous Components
10B 13010738	Fiber wall panel	No Asbestos Detected	55% Cellulose 25% Synthetic	10% Resin and Binder 10% Paint
11A 13010739	Rolled roofing field	No Asbestos Detected	15% Glass Fiber 5% Cellulose	45% Asphalt Filler and Binder 30% Rocks 5% Mineral Particles
11B 13010740	Rolled roofing field	No Asbestos Detected	15% Glass Fiber 5% Cellulose	45% Asphalt Filler and Binder 30% Rocks 5% Mineral Particles
11C 13010741	Rolled roofing field	No Asbestos Detected	15% Glass Fiber 5% Cellulose	45% Asphalt Filler and Binder 30% Rocks 5% Mineral Particles
12A 13010742	HVAC sealant, gray	No Asbestos Detected	10% Cellulose	85% Resin and Binder 5% Mineral Particles
12B 13010743	HVAC sealant, gray	No Asbestos Detected	10% Cellulose	85% Resin and Binder 5% Mineral Particles
13A 13010744	Vibration dampener	No Asbestos Detected	35% Synthetic 15% Glass Fiber	45% Rubber Particles 5% Mineral Particles
14A 13010745	Gray roofing mastic	5% Chrysotile Positive Stop		85% Asphalt Filler and Binder 10% Mineral Particles
	Layer Comments: First positive stop.			

This report relates only to the items tested. If samples are not collected by RGA Environmental personnel, accuracy of the results is limited by the methodology and expertise of the sample collector. Analyses are cross-checked with other laboratories for quality assurance purposes. This report shall not be reproduced except in full, without written approval of RGA Environmental. It shall not be used to claim product endorsement by NVLAP or any other agency of the U.S. Government.

Sampled By: Tedd Kattchee
 Received By: Abdulrazzak Mansur
 Reviewed By: Aruna Turaga

5/10/2013
 5/13/2013

Analyzed By: William Russell Browne
 Russell Browne 5/13/2013



1730 Minor Avenue, Suite 900, Seattle, WA 98101
 OFFICE: (206) 281-8858 FAX: (206) 281-8922 email: laboratory@rgaenv.com

Bulk Asbestos Fiber Analysis
 (EPA 600/R-93/116)



NVLAP LAB CODE 200613-0

Solano Community College

Project Location: Bldg 1100
 Solano Community College

RGA Batch Number: **13-1026**

RGA Project Number: **SCC32836**

Number of Samples: **33**

Report Key				
Client Sample ID	Layer ID (if applicable)	Asbestos Components	Non-Asbestos Fibrous Components	Non-Fibrous Components
RGA Lab ID	Layer Description			
	Layer Comments (if applicable)			
15A 13010747	2'x4' ceiling tile	No Asbestos Detected	55% Mineral Wool 10% Cellulose	30% Filler and Binder 5% Paint
15B 13010748	2'x4' ceiling tile	No Asbestos Detected	55% Mineral Wool 10% Cellulose	30% Filler and Binder 5% Paint

This report relates only to the items tested. If samples are not collected by RGA Environmental personnel, accuracy of the results is limited by the methodology and expertise of the sample collector. Analyses are cross-checked with other laboratories for quality assurance purposes. This report shall not be reproduced except in full, without written approval of RGA Environmental. It shall not be used to claim product endorsement by NVLAP or any other agency of the U.S. Government.

Sampled By: Tedd Kattchee
 Received By: Abdulrazzak Mansur 5/10/2013
 Reviewed By: Aruna Turaga 5/13/2013

Analyzed By: William Russell Browne
 Russell Browne 5/13/2013



ENVIRONMENTAL

PM - S. Steiner
steff@rgaenv.com
fax: 510.899.7051

PM - K. Schroeter
karin@rgaenv.com
fax: 510.899.7063

PM - K. Pilgrim
ken@rgaenv.com
fax: 510.899.7053

PM - T. Kattchee
tedd@rgaenv.com
fax: 510.899.7070

PM - B. Gils
bob@rgaenv.com
fax: 510.899.7050

PM - Marlin Bryant
marlin.bryant@rgaenv.com
fax: 510.899.7062

ACM BULK SAMPLE DATA SHEET

* PLM Analysis
 Stop Analysis at First Positive PAGE 2 OF 3
 Analyze All Samples
 Point Count Analysis (400-point)

Project Name/Address/Building No. : BLDG 1100

RGA Project: SCC 32836 Sampled By: TK Sample Date 5/7/13

Sample(s) Sent To: RGA EMSL Other: _____ TAT: _____ Rush 24Hrs 3-5 Days

*** FAX OR E-MAIL REPORT TO: SEE ABOVE PROJECT MANAGER (PM) ***

*** ADDITIONAL REPORT RECIPIENT(S): _____ ***

HM#	Material Description:	Sample Location & Material Location	Quantity:
1	1' ceiling Tile - NO MASTIC		
1A	1107 ceiling		
1B	1107 ceiling		
1C	1105 "		
7	EXTERIOR BROWN COATING		
7A	1107		
7B	1105		
8	USED MASTICS - Roof		40%
8A	1109 Roof PERIMETER		
8B	1107 "		
8C	1101 " SOUTH		
9	Roofing field Rolled		
9A	1109 Field SW CORNER		
9B	1107 " SE "		
9C	1101 " SOUTH EDGE		
10	FIBER WALL PANEL		
10A	1106 glass Room		
10B	1100 copy Room		

Relinquished By: TEDD KATTCHEE Signature: [Signature] Date/Time: 5/8/13
 Received By: Duane Flohra Signature: [Signature] Date/Time: MAY 09 2013/1507
 Relinquished By: _____ Signature: _____ Date/Time: _____
 Received By: RAZ MANSURD Signature: [Signature] Date/Time: 5/10/13



ENVIRONMENTAL

PM - S. Steiner
steff@rgaenv.com
fax: 510.899.7051

PM - K. Schroeter
karin@rgaenv.com
fax: 510.899.7063

PM - K. Pilgrim
ken@rgaenv.com
fax: 510.899.7053

PM - T. Kattchee
tedd@rgaenv.com
fax: 510.899.7070

PM - B. Gils
bob@rgaenv.com
fax: 510.899.7050

PM - Marlin Bryant
marlin.bryant@rgaenv.com
fax: 510.899.7062

ACM BULK SAMPLE DATA SHEET

* PLM Analysis
 Stop Analysis at First Positive PAGE 3 OF 3
 Analyze All Samples
 Point Count Analysis (400-point)

Project Name/Address/Building No. : BLDG 1100

RGA Project: SU 32836 Sampled By: TJR Sample Date 5/7/13

Sample(s) Sent To: RGA EMSL Other: TAT: Rush 24Hrs 3-5 Days

*** FAX OR E-MAIL REPORT TO: SEE ABOVE PROJECT MANAGER (PM) ***

*** ADDITIONAL REPORT RECIPIENT(S): _____ ***

HM#	Material Description:	Sample Location & Material Location	Quantity:
11	Roller Roofing Field		
11 A		1102 EAST SIDE	
11 B		1104 (NEW FOOT) WEST END	
11 C		1100 (OLD FOOT) WEST END	
12	HVAC Sealant (Grey)		
12 A		1104 HVAC UNIT DUCT	
12 B		" " " "	
13	Vibration Damper		
13 A		1104 HVAC UNIT	
14	Grey Roofing Mastics		
14 A		1100 NORTH PERIMETER	
14 B		1102 " "	
15	2x4 Ceiling Tile		
15 A		1106 CEILING DROP (NEW)	
15 B		1104 " " " "	

Relinquished By: TEDD KATTCHEE Signature: [Signature] Date/Time: 5/8/13

Received By: Duane Flohra Signature: [Signature] Date/Time: MAY 09 2013/ISO7

Relinquished By: TJR Signature: [Signature] Date/Time: 5/10/13

Received By: RAZ MANSUR Signature: [Signature] Date/Time: 5/10/13

Sample Log Chain of Custody

RGA Laboratory Services

INTERNAL

Client: _____ Client Contact _____

Company: Solano Community College

Client Address: 4000 Suisun Valley Road

Fairfield _____ CA _____ 94534- _____
City _____ State _____ Zip _____

Phone #: _____

2nd or Cell #: _____

Fax #: _____

e-mail Address: _____

Project Manager: Tedd Kattchee

Project Location: Bldg 1100
Solano Community College

Condition: Good Damaged Severe Damage

RGA Batch #: 13-1026

RGA Project #: SCC32836

Client Job #: _____

Number of Samples: 36

TYPE OF ANALYSIS		
ASBESTOS:	METALS:	
<input type="checkbox"/> PCM (air)	<input type="checkbox"/> Paint	<input type="checkbox"/> Soil
<input checked="" type="checkbox"/> PLM (bulk)	<input type="checkbox"/> Wipe	<input type="checkbox"/> Air
<input type="checkbox"/> Pt. Count (bulk)	<input type="checkbox"/> TCLP	<input type="checkbox"/> Water
MOLD: P&K <input type="checkbox"/> 100 <input type="checkbox"/> 101 <input type="checkbox"/> 102 <input type="checkbox"/> 105 <input type="checkbox"/> 117		
Other Method: _____		

Turn Around Time (other): <u>24 hour</u>		
2 hour / 4 hour	Same Day	One Day
Two Day	3-5 days	10 days
Price per Sample: \$ _____		

#	Client Sample ID	RGA Laboratory ID	Comments	#	Client Sample ID	RGA Laboratory ID	Comments
1	1A	13010713		11	2D	13010723	
2	1B	13010714		12	2E	13010724	
3	2A	13010715		13	2F	13010725	
4	2B	13010716		14	6A	13010726	
5	2C	13010717		15	6B	13010727	
6	3A	13010718		16	6C	13010728	
7	3B	13010719		17	7A	13010729	
8	4A	13010720		18	7B	13010730	
9	5A	13010721		19	8A	13010731	
10	5B	13010722		20	8B	13010732	

	Signature	Date	Time
Sampled by:	<u>TEDD KATTCHEE</u>	<u>5/7/13</u>	
Relinquished by:			
Received by:	<u>DUANE FLOHRA</u>	<u>5/9/13</u>	<u>1507</u>
Relinquished by:			
Received for Laboratory by:	<u>[Signature]</u>	<u>5/10/13</u>	<u>1627</u>
Analyzed by:	<u>[Signature]</u>	<u>5/13/13</u>	<u>1615</u>
Preliminary Results Reported to P.M. by:	<u>[Signature]</u>	<u>5/13/13</u>	
Final Report to P.M. by:			

Special Instructions: Stop analysis at first positive.
Due by 5/13/2013

Sample Log Chain of Custody



RGA Laboratory Services
INTERNAL

Client: _____ Client Contact _____
 Company: Solano Community College
 Client Address: 4000 Suisun Valley Road
 Fairfield CA 94534-
 City State Zip

RGA Batch #: 13-1026
 RGA Project #: SCC32836
 Client Job #: _____
 Number of Samples: 36

Page: 2 of 2

#	Client Sample ID	RGA Laboratory ID	Comments	#	Client Sample ID	RGA Laboratory ID	Comments
21	8C	13010733		41			
22	9A	13010734		42			
23	9B	13010735		43			
24	9C	13010736		44			
25	10A	13010737		45			
26	10B	13010738		46			
27	11A	13010739		47			
28	11B	13010740		48			
29	11C	13010741		49			
30	12A	13010742		50			
31	12B	13010743		51			
32	13A	13010744		52			
33	14A	13010745		53			
34	14B	13010746		54			
35	15A	13010747		55			
36	15B	13010748		56			
37				57			
38				58			
39				59			
40				60			

	Signature	Date	Time
Sampled by:	TEDD KATCHEE	5/7/13	
Relinquished by:			
Received by:	DUANE FLOHRA	5/9/13	1507
Relinquished by:			
Received for Laboratory by:		5/10/13	1023
Analyzed by:		5/13/13	16:15
Preliminary Results Reported to P.M. by:		5/13/13	
Final Report to P.M. by:			

Special Instructions: Stop analysis at first positive.
 Due by 5/13/2013

MICRO ANALYTICAL LABORATORIES, INC.
BULK ASBESTOS ANALYSIS - POLARIZED LIGHT MICROSCOPY (PLM)



1023
 Tedd Kattchee
 RGA Environmental, Inc.
 1466 66th Street
 Emeryville, CA 94608

PROJECT:
SOLANO COLLEGE
4000 SUISUN VALLEY ROAD
FAIRFIELD, CA
(BUILDING #1100)
PROJECT NO. SCC-29847

Micro Log In **185095**
 Total Samples 24
 Date Sampled 08/02/2013
 Date Received 08/02/2013
 Date Analyzed 08/02/2013

ASBESTOS INFORMATION

SAMPLE IDENTIFICATION

QUANTITY (AREA %) / TYPES / LAYERS / DISTINCT SAMPLES

**DOMINANT
OTHER MATERIALS**

Client #:	1A		
Micro #:	185095-01	Analyst: DA	
HM#1 - 12" VFT WITH YELLOW MASTIC - BEIGE VFT CENTER OF ROOM #1101			VFT: 3% CHRYSOTILE ASBESTOS MASTIC: NONE DETECTED
			Matrix: SYNTHETIC MATERIAL, Type: CARBONATE, ADHESIVE.
Client #:	1B		
Micro #:	185095-02	Analyst: DA	
HM#1 - 12" VFT WITH YELLOW MASTIC - BEIGE VFT AT ENTRANCE OF ROOM #1101			VFT: 3% CHRYSOTILE ASBESTOS MASTIC: NONE DETECTED
			Matrix: SYNTHETIC MATERIAL, Type: CARBONATE, ADHESIVE.
Client #:	1C		
Micro #:	185095-03	Analyst: DA GR	
HM#1 - 12" VFT WITH YELLOW MASTIC - BEIGE VFT SOUTHEAST CORNER OF ROOM #1101			VFT: 3% CHRYSOTILE ASBESTOS MASTIC: NONE DETECTED
			Matrix: SYNTHETIC MATERIAL, Type: CARBONATE, ADHESIVE.
Client #:	2A		
Micro #:	185095-04	Analyst: DA	
HM#2 - DRYWALL WITH JOINT COMPOUND SOUTH CORNER OF ROOM #1109 - MAIN OFFICE			DRYWALL: NONE DETECTED JOINT COMPOUND: NONE DETECTED TAPE / PAINT: NONE DETECTED
			10% CELLULOSE 2% FIBROUS GLASS Matrix: 'GYPSUM' (CALCIUM SULFATE), Type: CARBONATE.
Client #:	2B		
Micro #:	185095-05	Analyst: DA	
HM#2 - DRYWALL WITH JOINT COMPOUND WEST CORNER OF ROOM #1109 RESTROOM			DRYWALL: NONE DETECTED JOINT COMPOUND: NONE DETECTED PAINT: NONE DETECTED
			10% CELLULOSE 3% FIBROUS GLASS Matrix: 'GYPSUM' (CALCIUM SULFATE), Type: CARBONATE.

Technical Supervisor:


 Gamini Ranatunga, Ph.D.

8/2/2013

Date Reported

Analyses use Polarized Light Microscopy (PLM), Micro Analytical SOP PLM-101 (Rev. 1/4/2013). Basic techniques follow the EPA Interim Method for Bulk Insulation Samples (1982), and EPA-600/R93-116 (1993). The 1993 method covers all types of bulk materials and is based on the 1982 Method, with improved analytical techniques for layered samples as required for NESHAP compliance. Asbestos is quantified by calibrated visual estimation. Detection limit is material dependent. Detection of asbestos traces (much less than 1%) may not be reliable or reproducible by PLM. Weight % cannot be determined by PLM. Asbestos with diameter below ~1 µm may not be detected by PLM. Absence of asbestos in dust, debris, and some compact materials, including floor tiles, cannot be conclusively established by PLM, and should be confirmed by Transmission Electron Microscopy (TEM). Tremolite-asbestos or actinolite-asbestos may be indistinguishable by PLM from some similar, non-regulated amphiboles (e.g. the "Libby Amphiboles" richterite and winchite), and should be confirmed by TEM. The lower quantitation limit (reporting limit) of PLM estimation is 1%. The Cal-OSHA definition of asbestos-containing construction material is 0.1% asbestos; however, reliable determination of asbestos percent at this level cannot be done by PLM estimation; PLM Point Counting or TEM weight percent analysis are recommended. Only dominant non-asbestos materials are indicated. Interferences may prevent detection of small asbestos fibers, and hinder determination of some optical properties. Sample heterogeneity is indicated by listing more than one distinct layer or material on the report. Layers are analyzed separately when feasible; if asbestos is detected, percentages are reported for individual layers. Interlayer contamination is possible among any layers in a sample. The notation ND (or "NONE DETECTED") indicates a result of "NO ASBESTOS DETECTED" in a homogeneous sample, or in all layers of a heterogeneous sample. Composite asbestos percentages from multiple layers are applicable only to wallboard / joint compound systems; compositing is based on customers' descriptions of material as "joint compound". Customers are solely responsible for identification and description of bulk materials listed on field forms. Laboratory descriptions may differ from those given by customers. Quality Control (QC): all results have been determined to be within acceptance limits prior to reporting. Samples that were reanalyzed are denoted by two sets of analyst initials. AIHA Accredited Laboratory ID No. 101768. NVLAP Lab Code 101872-0. CA ELAP Certification #1037. Unless otherwise stated herein, all samples were received in acceptable condition for analysis. This report must not be used to claim product endorsement by NIST or any U.S. Government agency. This report shall not be reproduced except in full without the approval of Micro Analytical Laboratories, Inc., and pertains only to the samples analyzed.

MICRO ANALYTICAL LABORATORIES, INC.
BULK ASBESTOS ANALYSIS - POLARIZED LIGHT MICROSCOPY (PLM)




1023
 Tedd Kattchee
 RGA Environmental, Inc.
 1466 66th Street
 Emeryville, CA 94608

PROJECT:
SOLANO COLLEGE
4000 SUISUN VALLEY ROAD
FAIRFIELD, CA
(BUILDING #1100)
PROJECT NO. SCC-29847

Micro Log In **185095**
 Total Samples 24
 Date Sampled 08/02/2013
 Date Received 08/02/2013
 Date Analyzed 08/02/2013

SAMPLE IDENTIFICATION	ASBESTOS INFORMATION QUANTITY (AREA %) / TYPES / LAYERS / DISTINCT SAMPLES	DOMINANT OTHER MATERIALS
Client #: 2C Micro #: 185095-06 Analyst: DA HM#2 - DRYWALL WITH JOINT COMPOUND NORTHWEST CORNER OF ROOM #1109 - MAIN OFFICE	DRYWALL: NONE DETECTED JOINT COMPOUND: NONE DETECTED TAPE / PAINT: NONE DETECTED	10 % CELLULOSE 2 % FIBROUS GLASS Matrix: GYPSUM (CALCIUM SULFATE), Type: CARBONATE.
Client #: 3A Micro #: 185095-07 Analyst: DA HM#3 - WALL TEXTURE MAIN OFFICE OF ROOM #1109 SOUTH WALL	TEXTURE / PAINT: NONE DETECTED	Matrix: CARBONATE. Type:
Client #: 3B Micro #: 185095-08 Analyst: DA HM#3 - WALL TEXTURE MAIN OFFICE OF ROOM #1109 WEST WALL	TEXTURE / PAINT: NONE DETECTED	Matrix: CARBONATE. Type:
Client #: 3C Micro #: 185095-09 Analyst: DA GR HM#3 - WALL TEXTURE BACK WALL OF ROOM #1109 - EAST	TEXTURE / PAINT: NONE DETECTED	Matrix: CARBONATE. Type:
Client #: 4A Micro #: 185095-10 Analyst: DA HM#4 - 4" GRAY COVE BASE WITH BEIGE MASTIC EAST WALL MAIN OFFICE ROOM #1109	COVE BASE: NONE DETECTED MASTIC: NONE DETECTED	Matrix: SYNTHETIC MATERIAL, Type: CARBONATE.

Technical Supervisor: 

Gamini Ranatunga, Ph.D.

8/2/2013

Date Reported

Analyses use Polarized Light Microscopy (PLM), Micro Analytical SOP PLM-101 (Rev. 1/4/2013). Basic techniques follow the EPA Interim Method for Bulk Insulation Samples (1982), and EPA-600/R93-116 (1993). The 1993 method covers all types of bulk materials and is based on the 1982 Method, with improved analytical techniques for layered samples as required for NESHAP compliance. Asbestos is quantified by calibrated visual estimation. Detection limit is material dependent. Detection of asbestos traces (much less than 1%) may not be reliable or reproducible by PLM. Weight % cannot be determined by PLM. Asbestos with diameter below ~1 µm may not be detected by PLM. Absence of asbestos in dust, debris, and some compact materials, including floor tiles, cannot be conclusively established by PLM, and should be confirmed by Transmission Electron Microscopy (TEM). Tremolite-asbestos or actinolite-asbestos may be indistinguishable by PLM from some similar, non-regulated amphiboles (e.g. the "Libby Amphiboles" richterite and winchite), and should be confirmed by TEM. The lower quantitation limit (reporting limit) of PLM estimation is 1%. The Cal-OSHA definition of asbestos-containing construction material is 0.1% asbestos; however, reliable determination of asbestos percent at this level cannot be done by PLM estimation; PLM Point Counting or TEM weight percent analysis are recommended. Only dominant non-asbestos materials are indicated. Interferences may prevent detection of small asbestos fibers, and hinder determination of some optical properties. Sample heterogeneity is indicated by listing more than one distinct layer or material on the report. Layers are analyzed separately when feasible; if asbestos is detected, percentages are reported for individual layers. Interlayer contamination is possible among any layers in a sample. The notation ND (or "NONE DETECTED") indicates a result of "NO ASBESTOS DETECTED" in a homogeneous sample, or in all layers of a heterogeneous sample. Composite asbestos percentages from multiple layers are applicable only to wallboard / joint compound systems; compositing is based on customers' descriptions of material as "joint compound". Customers are solely responsible for identification and description of bulk materials listed on field forms. Laboratory descriptions may differ from those given by customers. Quality Control (QC): all results have been determined to be within acceptance limits prior to reporting. Samples that were reanalyzed are denoted by two sets of analyst initials. AIHA Accredited Laboratory ID No. 101768. NVLAP Lab Code 101872-0. CA ELAP Certification #1037. Unless otherwise stated herein, all samples were received in acceptable condition for analysis. This report must not be used to claim product endorsement by NIST or any U.S. Government agency. This report shall not be reproduced except in full without the approval of Micro Analytical Laboratories, Inc., and pertains only to the samples analyzed.

MICRO ANALYTICAL LABORATORIES, INC.
BULK ASBESTOS ANALYSIS - POLARIZED LIGHT MICROSCOPY (PLM)



1023
 Tedd Kattchee
 RGA Environmental, Inc.
 1466 66th Street
 Emeryville, CA 94608

PROJECT:
SOLANO COLLEGE
4000 SUISUN VALLEY ROAD
FAIRFIELD, CA
(BUILDING #1100)
PROJECT NO. SCC-29847

Micro Log In **185095**
 Total Samples 24
 Date Sampled 08/02/2013
 Date Received 08/02/2013
 Date Analyzed 08/02/2013


ASBESTOS INFORMATION

SAMPLE IDENTIFICATION

QUANTITY (AREA %) / TYPES / LAYERS / DISTINCT SAMPLES

DOMINANT
OTHER MATERIALS

Client #: 4B Micro #: 185095-11 Analyst: DA HM#4 - 4" GRAY COVE BASE WITH BEIGE MASTIC WEST WALL MAIN OFFICE ROOM #1109	COVE BASE: NONE DETECTED MASTIC: NONE DETECTED COMPOUND: NONE DETECTED	Matrix: SYNTHETIC MATERIAL, Type: CARBONATE.
Client #: 5A Micro #: 185095-12 Analyst: DA HM#5 - 4" BROWN COVE BASE WITH BEIGE MASTIC RESTROOM OF ROOM #1109	COVE BASE: NONE DETECTED MASTIC: NONE DETECTED COMPOUND: NONE DETECTED	Matrix: SYNTHETIC MATERIAL, Type: CARBONATE.
Client #: 6A Micro #: 185095-13A Analyst: DA HM#6 - 12" GRAY AND TAN MULTI COLOR FLOOR TILE - 2 LAYERS WITH BLACK MASTIC RESTROOM OF ROOM #1109 LAB NOTE: TAN FLOOR TILE	FLOOR TILE (TAN): NONE DETECTED MASTIC: NONE DETECTED	Matrix: SYNTHETIC MATERIAL, Type: CARBONATE, ADHESIVE.
Client #: 6A Micro #: 185095-13B Analyst: DA HM#6 - 12" GRAY AND TAN MULTI COLOR FLOOR TILE - 2 LAYERS WITH BLACK MASTIC RESTROOM OF ROOM #1109 LAB NOTE: PEBBLE PATTERN FLOORING	FLOORING: NONE DETECTED BACKING: NONE DETECTED MASTIC: NONE DETECTED	5 % CELLULOSE 5 % FIBROUS GLASS 5 % SYNTHETIC FIBERS Matrix: SYNTHETIC MATERIAL, Type: CARBONATE, ADHESIVE.
Client #: 6B Micro #: 185095-14A Analyst: DA GR HM#6 - 12" GRAY AND TAN MULTI COLOR FLOOR TILE - 2 LAYERS WITH BLACK MASTIC RESTROOM OF ROOM #1109 LAB NOTE: TAN FLOOR TILE	FLOOR TILE: NONE DETECTED MASTIC: NONE DETECTED	Matrix: SYNTHETIC MATERIAL, Type: CARBONATE, ADHESIVE.

Technical Supervisor:  8/2/2013
 Gamini Ranatunga, Ph.D. Date Reported

Analyses use Polarized Light Microscopy (PLM), Micro Analytical SOP PLM-101 (Rev. 1/4/2013). Basic techniques follow the EPA Interim Method for Bulk Insulation Samples (1982), and EPA-600/R93-116 (1993). The 1993 method covers all types of bulk materials and is based on the 1982 Method, with improved analytical techniques for layered samples as required for NESHAP compliance. Asbestos is quantified by calibrated visual estimation. Detection limit is material dependent. Detection of asbestos traces (much less than 1%) may not be reliable or reproducible by PLM. Weight % cannot be determined by PLM. Asbestos with diameter below $\sim 1 \mu\text{m}$ may not be detected by PLM. Absence of asbestos in dust, debris, and some compact materials, including floor tiles, cannot be conclusively established by PLM, and should be confirmed by Transmission Electron Microscopy (TEM). Tremolite-asbestos or actinolite-asbestos may be indistinguishable by PLM from some similar, non-regulated amphiboles (e.g. the "Libby Amphiboles" richterite and winchite), and should be confirmed by TEM. The lower quantitation limit (reporting limit) of PLM estimation is 1%. The Cal-OSHA definition of asbestos-containing construction material is 0.1% asbestos; however, reliable determination of asbestos percent at this level cannot be done by PLM estimation; PLM Point Counting or TEM weight percent analysis are recommended. Only dominant non-asbestos materials are indicated. Interferences may prevent detection of small asbestos fibers, and hinder determination of some optical properties. Sample heterogeneity is indicated by listing more than one distinct layer or material on the report. Layers are analyzed separately when feasible; if asbestos is detected, percentages are reported for individual layers. Interlayer contamination is possible among any layers in a sample. The notation ND (or "NONE DETECTED") indicates a result of "NO ASBESTOS DETECTED" in a homogeneous sample, or in all layers of a heterogeneous sample. Composite asbestos percentages from multiple layers are applicable only to wallboard / joint compound systems; compositing is based on customers' descriptions of material as "joint compound". Customers are solely responsible for identification and description of bulk materials listed on field forms. Laboratory descriptions may differ from those given by customers. Quality Control (QC): all results have been determined to be within acceptance limits prior to reporting. Samples that were reanalyzed are denoted by two sets of analyst initials. ALHA Accredited Laboratory ID No. 101768. NVLAP Lab Code 101872-0. CA ELAP Certification #1037. Unless otherwise stated herein, all samples were received in acceptable condition for analysis. This report must not be used to claim product endorsement by NIST or any U.S. Government agency. This report shall not be reproduced except in full without the approval of Micro Analytical Laboratories, Inc., and pertains only to the samples analyzed.

MICRO ANALYTICAL LABORATORIES, INC.
BULK ASBESTOS ANALYSIS - POLARIZED LIGHT MICROSCOPY (PLM)



1023
 Tedd Kattchee
 RGA Environmental, Inc.
 1466 66th Street
 Emeryville, CA 94608

PROJECT:
SOLANO COLLEGE
4000 SUISUN VALLEY ROAD
FAIRFIELD, CA
(BUILDING #1100)
PROJECT NO. SCC-29847

Micro Log In **185095**
 Total Samples 24
 Date Sampled 08/02/2013
 Date Received 08/02/2013
 Date Analyzed 08/02/2013


ASBESTOS INFORMATION

SAMPLE IDENTIFICATION

QUANTITY (AREA %) / TYPES / LAYERS / DISTINCT SAMPLES

DOMINANT
OTHER MATERIALS

Client #: 6B Micro #: 185095-14B Analyst: DA HM#6 - 12" GRAY AND TAN MULTI COLOR FLOOR TILE - 2 LAYERS WITH BLACK MASTIC RESTROOM OF ROOM #1109 LAB NOTE: PEBBLE PATTERN FLOORING	FLOORING: NONE DETECTED BACKING: NONE DETECTED MASTIC: NONE DETECTED	5% CELLULOSE 5% FIBROUS GLASS 5% SYNTHETIC FIBERS Matrix: SYNTHETIC MATERIAL, Type: CARBONATE, ADHESIVE.
Client #: 7A Micro #: 185095-15 Analyst: DA HM#7 - 12" OFF WHITE FLOOR TILE UNDER CARPETS MAIN OFFICE CENTER ROOM #1109	FLOOR TILE: 4% CHRYSOTILE ASBESTOS MASTIC (YELLOW): NONE DETECTED MASTIC (BLACK): NONE DETECTED	3% CELLULOSE Matrix: SYNTHETIC MATERIAL, Type: CARBONATE, ADHESIVE.
Client #: 7B Micro #: 185095-16 Analyst: DA GR HM#7 - 12" OFF WHITE FLOOR TILE UNDER CARPETS NORTHEAST OFFICE ROOM #1109	FLOOR TILE: 4% CHRYSOTILE ASBESTOS MASTIC (YELLOW): NONE DETECTED MASTIC (BLACK): NONE DETECTED	3% CELLULOSE 2% SYNTHETIC FIBERS Matrix: SYNTHETIC MATERIAL, Type: CARBONATE, ADHESIVE.
Client #: 7C Micro #: 185095-17 Analyst: DA HM#7 - 12" OFF WHITE FLOOR TILE UNDER CARPETS NORTHWEST OFFICE ROOM #1109	FLOOR TILE: 4% CHRYSOTILE ASBESTOS MASTIC (YELLOW): NONE DETECTED MASTIC (BLACK): NONE DETECTED	3% CELLULOSE Matrix: SYNTHETIC MATERIAL, Type: CARBONATE, ADHESIVE.
Client #: 8A Micro #: 185095-18 Analyst: DA HM#8 - WHITE CARPET MASTIC MAIN OFFICE CENTER	NONE DETECTED	3% SYNTHETIC FIBERS Matrix: SYNTHETIC MATERIAL Type:

Technical Supervisor: 

8/2/2013

Gamini Ranatunga, Ph.D.

Date Reported

Analyses use Polarized Light Microscopy (PLM), Micro Analytical SOP PLM-101 (Rev. 1/4/2013). Basic techniques follow the EPA Interim Method for Bulk Insulation Samples (1982), and EPA-600/R93-116 (1993). The 1993 method covers all types of bulk materials and is based on the 1982 Method, with improved analytical techniques for layered samples as required for NESHAP compliance. Asbestos is quantified by calibrated visual estimation. Detection limit is material dependent. Detection of asbestos traces (much less than 1%) may not be reliable or reproducible by PLM. Weight % cannot be determined by PLM. Asbestos with diameter below $\sim 1 \mu\text{m}$ may not be detected by PLM. Absence of asbestos in dust, debris, and some compact materials, including floor tiles, cannot be conclusively established by PLM, and should be confirmed by Transmission Electron Microscopy (TEM). Tremolite-asbestos or actinolite-asbestos may be indistinguishable by PLM from some similar, non-regulated amphiboles (e.g. the "Libby Amphiboles" richterite and winchite), and should be confirmed by TEM. The lower quantitation limit (reporting limit) of PLM estimation is 1%. The Cal-OSHA definition of asbestos-containing construction material is 0.1% asbestos; however, reliable determination of asbestos percent at this level cannot be done by PLM estimation; PLM Point Counting or TEM weight percent analysis are recommended. Only dominant non-asbestos materials are indicated. Interferences may prevent detection of small asbestos fibers, and hinder determination of some optical properties. Sample heterogeneity is indicated by listing more than one distinct layer or material on the report. Layers are analyzed separately when feasible; if asbestos is detected, percentages are reported for individual layers. Interlayer contamination is possible among any layers in a sample. The notation ND (or "NONE DETECTED") indicates a result of "NO ASBESTOS DETECTED" in a homogeneous sample, or in all layers of a heterogeneous sample. Composite asbestos percentages from multiple layers are applicable only to wallboard / joint compound systems; compositing is based on customers' descriptions of material as "joint compound". Customers are solely responsible for identification and description of bulk materials listed on field forms. Laboratory descriptions may differ from those given by customers. Quality Control (QC): all results have been determined to be within acceptance limits prior to reporting. Samples that were reanalyzed are denoted by two sets of analyst initials. ALHA Accredited Laboratory ID No. 101768. NVLAP Lab Code 101872-0. CA ELAP Certification #1037. Unless otherwise stated herein, all samples were received in acceptable condition for analysis. This report must not be used to claim product endorsement by NIST or any U.S. Government agency. This report shall not be reproduced except in full without the approval of Micro Analytical Laboratories, Inc., and pertains only to the samples analyzed.

MICRO ANALYTICAL LABORATORIES, INC.
BULK ASBESTOS ANALYSIS - POLARIZED LIGHT MICROSCOPY (PLM)



1023
 Tedd Kattchee
 RGA Environmental, Inc.
 1466 66th Street
 Emeryville, CA 94608

PROJECT:
SOLANO COLLEGE
4000 SUI SUN VALLEY ROAD
FAIRFIELD, CA
(BUILDING #1100)
PROJECT NO. SCC-29847

Micro Log In **185095**
 Total Samples 24
 Date Sampled 08/02/2013
 Date Received 08/02/2013
 Date Analyzed 08/02/2013

ASBESTOS INFORMATION

SAMPLE IDENTIFICATION	QUANTITY (AREA %) / TYPES / LAYERS / DISTINCT SAMPLES	DOMINANT OTHER MATERIALS
Client #: 8B Micro #: 185095-19 Analyst: DA HM#8 - WHITE CARPET MASTIC NORTHEAST OFFICE CENTER	NONE DETECTED	3 % SYNTHETIC FIBERS Matrix: SYNTHETIC MATERIAL Type:
Client #: 9A Micro #: 185095-20 Analyst: DA HM#9 - FIBERBOARD WALLS WITH JOINT COMPOUND WEST PERIMETER WALL SOUTHWEST CORNER	FIBERBOARD: NONE DETECTED WALL COVERING: NONE DETECTED JOINT COMPOUND: NONE DETECTED	80 % CELLULOSE Matrix: SYNTHETIC MATERIAL, Type: CARBONATE.
Client #: 9B Micro #: 185095-21 Analyst: DA HM#9 - FIBERBOARD WALLS WITH JOINT COMPOUND EAST PERIMETER WALL SOUTHEAST CORNER IN RESTROOM	FIBERBOARD: NONE DETECTED WALL COVERING: NONE DETECTED JOINT COMPOUND: NONE DETECTED	80 % CELLULOSE Matrix: SYNTHETIC MATERIAL, Type: CARBONATE.
Client #: 9C Micro #: 185095-22 Analyst: DA HM#9 - FIBERBOARD WALLS WITH JOINT COMPOUND NORTHEAST PERIMETER WALL NORTHEAST CORNER	FIBERBOARD: NONE DETECTED WALL COVERING: NONE DETECTED JOINT COMPOUND: NONE DETECTED	80 % CELLULOSE Matrix: SYNTHETIC MATERIAL, Type: CARBONATE.

Technical Supervisor:  8/2/2013
 Gamini Ranatunga, Ph.D. Date Reported

Analyses use Polarized Light Microscopy (PLM), Micro Analytical SOP PLM-101 (Rev. 1/4/2013). Basic techniques follow the EPA Interim Method for Bulk Insulation Samples (1982), and EPA-600/R93-116 (1993). The 1993 method covers all types of bulk materials and is based on the 1982 Method, with improved analytical techniques for layered samples as required for NESHAP compliance. Asbestos is quantified by calibrated visual estimation. Detection limit is material dependent. Detection of asbestos traces (much less than 1%) may not be reliable or reproducible by PLM. Weight % cannot be determined by PLM. Asbestos with diameter below ~1 µm may not be detected by PLM. Absence of asbestos in dust, debris, and some compact materials, including floor tiles, cannot be conclusively established by PLM, and should be confirmed by Transmission Electron Microscopy (TEM). Tremolite-asbestos or actinolite-asbestos may be indistinguishable by PLM from some similar, non-regulated amphiboles (e.g. the "Libby Amphiboles" richterite and winchite), and should be confirmed by TEM. The lower quantitation limit (reporting limit) of PLM estimation is 1%. The Cal-OSHA definition of asbestos-containing construction material is 0.1% asbestos; however, reliable determination of asbestos percent at this level cannot be done by PLM estimation; PLM Point Counting or TEM weight percent analysis are recommended. Only dominant non-asbestos materials are indicated. Interferences may prevent detection of small asbestos fibers, and hinder determination of some optical properties. Sample heterogeneity is indicated by listing more than one distinct layer or material on the report. Layers are analyzed separately when feasible; if asbestos is detected, percentages are reported for individual layers. Interlayer contamination is possible among any layers in a sample. The notation ND (or "NONE DETECTED") indicates a result of "NO ASBESTOS DETECTED" in a homogeneous sample, or in all layers of a heterogeneous sample. Composite asbestos percentages from multiple layers are applicable only to wallboard / joint compound systems; compositing is based on customers' descriptions of material as "joint compound". Customers are solely responsible for identification and description of bulk materials listed on field forms. Laboratory descriptions may differ from those given by customers. Quality Control (QC): all results have been determined to be within acceptance limits prior to reporting. Samples that were reanalyzed are denoted by two sets of analyst initials. AIHA Accredited Laboratory ID No. 101768. NVLAP Lab Code 101872-0. CA ELAP Certification #1037. Unless otherwise stated herein, all samples were received in acceptable condition for analysis. This report must not be used to claim product endorsement by NIST or any U.S. Government agency. This report shall not be reproduced except in full without the approval of Micro Analytical Laboratories, Inc., and pertains only to the samples analyzed.



ENVIRONMENTAL

PM - S. Steiner
steff@rgaenv.com
fax: 510.899.7051

PM - K. Schroeter
karin@rgaenv.com
fax: 510.899.7063

PM - K. Pilgrim
ken@rgaenv.com
fax: 510.899.7053

PM - T. Kattchee
tedd@rgaenv.com
fax: 510.899.7070

PM - B. Gils
bob@rgaenv.com
fax: 510.899.7050

PM - Marlin Bryant
marlin.bryant@rgaenv.com
fax: 510.899.7062

ACM BULK SAMPLE DATA SHEET

* PLM Analysis

___ Stop Analysis at First Positive

PAGE 1 OF 4

Analyze All Samples

___ Point Count Analysis (400-point)

185095

Project Name/Address/Building No.: Solano College - 4000 Suisun Valley rd Fairfield CA (Building #1100)

RGA Project: SCC-09847

Sampled By: Steve Rogers

Sample Date 8-2-13

Sample(s) Sent To: ___ RGA ___ EMSL

Other: MAC

TAT: ___

Rush 24Hrs

___ 3-5 Days

*** **FAX OR E-MAIL REPORT TO: SEE ABOVE PROJECT MANAGER (PM)** ***

*** ADDITIONAL REPORT RECIPIENT(S): _____ ***

HM#	Sample ID	Material Description	Sample Location & Material Location	Quantity
1		12" UFT with yellow mastic - Beige UFT		
	1-A		Center of room #1101	1200
	1-B		at entrance of room #1101	
	1-C		Southeast corner of room #1101	
2		Drywall with 3/c		
	2-A		South corner of room #1109 - main office	1000
	2-B		West corner of room #1109 restroom	
	2-C		Northwest corner of room #1109 - main office	
3		Wall texture		
	3-A		Main office of room #1109 South wall	Throughout
	3-B		Main office of room #1109 west wall	
	3-C		Back wall of room #1109 - East	
4		4" Gray cove base with beige mastic		
	4-A		East wall main office room #1109	50 ft
	4-B		West wall main office room #1109	
	C			
5		4" Brown cove base with beige mastic		
	5-A		Restroom of room #1109	
	B			
	C			
	D			
	E			
	F			
	G			

Relinquished By: Steve Rogers

Signature: [Signature]

Date/Time: 8-2-13-1230

Received By: _____

Signature: _____

Date/Time: 8/2/13 1241

Relinquished By: _____

Signature: _____

Date/Time: _____

Received By: _____

Signature: _____

Date/Time: _____



ENVIRONMENTAL

PM - S. Steiner
steff@rgaenv.com
fax: 510.899.7051

PM - K. Schroeter
karin@rgaenv.com
fax: 510.899.7063

PM - K. Pilgrim
ken@rgaenv.com
fax: 510.899.7053

PM - T. Kattchee
tedd@rgaenv.com
fax: 510.899.7070

PM - B. Gils
bob@rgaenv.com
fax: 510.899.7050

PM - Marlin Bryant
marlin.bryant@rgaenv.com
fax: 510.899.7062

ACM BULK SAMPLE DATA SHEET

* PLM Analysis

Stop Analysis at First Positive

Analyze All Samples

Point Count Analysis (400-point)

PAGE 2 OF 2
198095

Project Name/Address/Building No.: Solano College 4000 Swiss Valley rd Fairfield CA (Building #400)

RGA Project: SCC-29847 Sampled By: J. Rogers Sample Date 8-2-13

Sample(s) Sent To: RGA EMSL Other: MAC TAT: 24 Hrs Rush 24 Hrs 3-5 Days

*** FAX OR E-MAIL REPORT TO: SEE ABOVE PROJECT MANAGER (PM) ***

*** ADDITIONAL REPORT RECIPIENT(S): _____ ***

HM#	Material Description:	Sample ID	Sample Location & Material Location	Quantity:
6	12" Gray & Tan multi color floor tile - 2 layers with black mastic			
		6-A	Restroom of room #1109	500
		6-B	Restroom of room #1109	
		C		
7	12" off white floor tile under carpets			
		7-A	Main office center room #1109	1300
		7-B	NE office room #1109	Throughout
		7-C	NW office room #1109	
8	White carpet mastic			
		8-A	Main office center	1300
		8-B	NE office center	Throughout
		C		
9	Fiberboard walls with s/c			
		9-A	West perimeter wall SW corner	1800
		9-B	East perimeter wall SE corner in restroom	
		9-C	NE perimeter wall NE corner	
		A		
		B		
		C		
		D		
		E		
		F		
		G		

Relinquished By: Steve Rogers Signature: [Signature] Date/Time: 8-2-13-12:30

Received By: _____ Signature: _____ Date/Time: 8/2/13 12:41

Relinquished By: _____ Signature: _____ Date/Time: _____

Received By: _____ Signature: _____ Date/Time: _____

Appendix 2

Laboratory Results and Chain of Custody – Lead



May 13, 2013

RGA Batch # 13-1025

Client: Client Contact
Company: Solano Community College
4000 Suisun Valley Road
Fairfield, CA, 94534

Project: Bldg 1100 Solano Comm Colge
Matrix: Paint Chips - Total Lead
Date Sampled: 5/7/2013
Date Received: 5/10/2013
Date Analyzed: 5/13/2013

Project #: SCC32836
P.O. #: N/A
Sampled By: Tedd K
Method: EPA SW-846 Method 7420
Analyst: *Aruna Turaga*

LEAD SAMPLE RESULTS

RGA Lab ID	Client ID	RL (mg/kg)	Concentration (mg/kg)	Percent %
13010711	Pb-1	19	4,400	0.440
13010712	Pb-2	1900	3,600	0.360

QA/QC Results
Batch QC MS
Method Blank

110% Recovery
<0.5 ug/ml

RL - reporting limit
mg - milligrams
kg - kilograms
< - less than

Reviewed by:

Dr. Aruna Turaga, Laboratory Director

13-1025



PM - S. Steiner
steff@rgaenv.com
fax: 510.899.7051

PM - K. Schroeter
karin@rgaenv.com
fax: 510.899.7063

PM - K. Pilgrim
ken@rgaenv.com
fax: 510.899.7053

PM - T. Kattchee
tedd@rgaenv.com
fax: 510.899.7070

PM - B. Gils
bob@rgaenv.com
fax: 510.899.7050

PM - Marlin Bryant
marlin.bryant@rgaenv.com
fax: 510.899.7062

LEAD PAINT SAMPLE DATA SHEET

* Lead Analysis
 Flame AA (EPA 7420)
___ TTLC

PAGE 1 OF 1

Project Name/Address/Building No.: BLDG 1100 SALAND COMM COLLEGE

RGA Project #: SCC 32836 Sampled By: TK Sampling Date 5/7/13

Sample(s) Sent To: RGA EMSL Other: TAT: Rush 24Hrs 3-5 Days

FAX OR E-MAIL REPORT TO: SEE ABOVE PROJECT MANAGER (PM)

ADDITIONAL REPORT RECIPIENT(S): _____

Sample ID	Paint Description and Sample Location	Condition (I/F/P)
Pb-1	Paint Color: <u>BRW</u> Substrate: <u>WOOD</u> Component: <u>wall</u> Sample Location: Bldg. # <u>1100</u> Unit # _____ Room _____ <u>EXTERIOR</u>	P
Pb-2	Paint Color: <u>DARK BRW</u> Substrate: <u>WOOD</u> Component: <u>TRIM</u> Sample Location: Bldg. # <u>110A</u> Unit # _____ Room _____ <u>EXTERIOR</u>	P
	Paint Color: _____ Substrate: _____ Component: _____ Sample Location: Bldg. # _____ Unit # _____ Room _____	
	Paint Color: _____ Substrate: _____ Component: _____ Sample Location: Bldg. # _____ Unit # _____ Room _____	
	Paint Color: _____ Substrate: _____ Component: _____ Sample Location: Bldg. # _____ Unit # _____ Room _____	
	Paint Color: _____ Substrate: _____ Component: _____ Sample Location: Bldg. # _____ Unit # _____ Room _____	
	Paint Color: _____ Substrate: _____ Component: _____ Sample Location: Bldg. # _____ Unit # _____ Room _____	

Relinquished By: TEDD KATTCHEE Signature: [Signature] Date/Time: 5/8/13

Received By: Duane Flohra Signature: [Signature] Date/Time: MAY 09 2013/1515

Relinquished By: _____ Signature: _____ Date/Time: _____

Received By: RAZ MANSURD Signature: [Signature] Date/Time: 5/10/13

Sample Log Chain of Custody

RGA Laboratory Services
INTERNAL

Client: _____ Client Contact _____
 Company: Solano Community College
 Client Address: 4000 Suisun Valley Road
 Fairfield CA 94534-
 City State Zip
 Phone #: _____
 2nd or Cell #: _____
 Fax #: _____
 e-mail Address: _____

RGA Batch #: 13-1025
 RGA Project #: SCC32836
 Client Job #: _____
 Number of Samples: 2

TYPE OF ANALYSIS		
ASBESTOS:	METALS: <u>Pb</u>	
<input type="checkbox"/> PCM (air)	<input checked="" type="checkbox"/> Paint	<input type="checkbox"/> Soil
<input type="checkbox"/> PLM (bulk)	<input type="checkbox"/> Wipe	<input type="checkbox"/> Air
<input type="checkbox"/> Pt. Count (bulk)	<input type="checkbox"/> TCLP	<input type="checkbox"/> Water
MOLD: P&K <input type="checkbox"/> 100 <input type="checkbox"/> 101 <input type="checkbox"/> 102 <input type="checkbox"/> 105 <input type="checkbox"/> 117		
Other Method: _____		

Project Manager: Tedd Kattchee

Project Location: BLDG 1100
Solano Community College

Turn Around Time (other): 24 hour		
2 hour / 4 hour	Same Day	One Day
Two Day	3-5 days	10 days
Price per Sample:		\$ _____

Condition: Good Damaged Severe Damage

#	Client Sample ID	RGA Laboratory ID	Comments	#	Client Sample ID	RGA Laboratory ID	Comments
1	Pb-1	13010711		11			
2	Pb-2	13010712		12			
3				13			
4				14			
5				15			
6				16			
7				17			
8				18			
9				19			
10				20			

	Signature	Date	Time
Sampled by:	<u>TEDD KATTCHEE</u>	<u>5/7/13</u>	
Relinquished by:			
Received by:	<u>DUANE FLOHRA</u>	<u>5/9/13</u>	<u>1515</u>
Relinquished by:			
Received for Laboratory by:	<u>[Signature]</u>	<u>5/10/13</u>	<u>1013</u>
Analyzed by:	<u>[Signature]</u>	<u>5/13/13</u>	<u>12:00</u>
Preliminary Results Reported to P.M. by:	<u>[Signature]</u>	<u>5/13/13</u>	
Final Report to P.M. by:			



Special Instructions:
 Due by 5/13/2013

Appendix 3

Sample and Material Location Diagram

SHEET NOTES

- ① ABATE ALL WALLBOARD AND ASSOCIATED COMPOUND
- ② ABATE ALL GREY ROOFING MASTICS



DRAWING IS DIAGRAMATIC

A. THIS WORK INCLUDES THE ABATEMENT OF WALLBOARD AND JOINT COMPOUND, VINYL FLOOR TILE (MASTIC IS NEGATIVE) AND GRAY ROOFING MASTICS THAT CONTAIN ASBESTOS LOCATED AT THE PORTABLES. ALL ITEMS INDICATED TO BE REMOVED OR ABATED MUST BE VERIFIED AND REVIEW ON SITE BY THE CONTRACTOR PRIOR TO BIDDING. ALL ABATEMENT WORK SHALL BE CONDUCTED IN ACCORDANCE WITH DISTRICT PROVIDED ASBESTOS ABATEMENT SPECIFICATION. CONTRACTOR TO PROVIDE A UNIT PRICE FOR ALL KNOWN OR ASSUMED ASBESTOS CONTAINING MATERIALS. A PLUS OR MINUS 10% OF QUANTITIES BID IS NOT CONSIDERED A CHANGE CONDITION.

B. PRIOR TO COMMENCEMENT OF ANY DEMOLITION WORK, THE CONTRACTOR SHALL THOROUGHLY REVIEW SITE AND ABATEMENT DRAWING FOR ANY DISCREPANCIES OR QUESTIONS TO THE COMMUNITY COLLEGE.

C. REFER TO THE ABATEMENT SPECIFICATIONS & SURVEY FOR INFORMATION PERTAINING TO ASBESTOS AND LEAD CONTENT.

D. NOTE HIDDEN MATERIALS MAYBE DISCOVERED DURING ABATEMENT. CONTACT THE COLLEGE REPRESENTATIVE IF ANY SUSPECT MATERIALS ARE FOUND DURING ABATEMENT

E. ALL SHEET NOTES ARE TYPICAL (TYP) UNLESS OTHERWISE NOTED. ABATE AND PROPERLY DISPOSE OF ALL ASBESTOS CONTAINING MATERIALS FROM THE BUILDING AND SURROUND AREA IMPACTED BY THE PLANNED DEMOLITION OF THE PORTABLES.

F. ABATE ALL LOOSE AND STRATIFIED LEAD PAINT FROM THE INTERIOR AND EXTERIOR OF THE PORTABLES IN ACCORDANCE WITH CAL-OSHA 1532.1. USING DUST CONTROL METHODS AND BY PROPERLY TRAINED PERSONNEL.

G. REMOVE AND PROPERLY DISPOSE OF ANY PCB-CONTAINING FLUORESCENT LIGHTING BALLASTS.

H. REMOVE AND RECYCLE MERCURY LIGHTING TUBES AND MERCURY THERMOSTATS FOUND THROUGHOUT THE BUILDING.

I. RECLAIM ANY REFRIGERANTS PRIOR TO ABATEMENT OR DEMOLITION OF MECHANICAL SYSTEMS.

J. REMOVE AND RECYCLE ANY METAL COMPONENTS SCHEDULED FOR DEMOLITION.

O. REMOVE AND CLEAN WITH A DISINFECTANT SOLUTION ANY ANIMAL CARCASSES OR FECAL MATTER THAT MAYBE ENCOUNTERED DURING DEMOLITION ACTIVITIES. PPE SHALL CONSIST OF SUITS, 1/2 FACE RESPIRATORS AND NITRILE GLOVES. NOTE FERAL CATS HAVE BEEN REPORTED TO LIVE UNDER THE PORTABLES.

P. THE CONTRACTOR CAN DEMOLISH THE <1% WALLBOARD IN PLACE. THE CONTRACTOR OPERATING THE EQUIPMENT MUST HOLD THE CSLB ASB LICENCE. THE DEMOLITION WORK IS A CAL-OSHA CLASS II ACTIVITY THE EMPLOYEE MUST HAVE PROPER ASBESTOS WORKER TRAINING.

APPROXIMATE MATERIAL QUANTITY

WALLBOARD & JOINT COMPOUND	2,200 SF
GREY ROOFING MASTICS	40 SF
VINYL FLOOR TILE ONLY	2500 SF



ASBESTOS ABATEMENT PLAN

Asbestos and Lead Sample Material Location Diagram

SURVEY DOCUMENTS	5/21/13
DESCRIPTION	DATE

SOLANO COMMUNITY COLLEGE
BUILDING 1100
4000 SIUSUN VALLEY ROAD FAIRFIELD CALIFORNIA

Drawing No.

1A

Appendix 4

Inspector Certificates

State of California
Division of Occupational Safety and Health
Certified Asbestos Consultant

Theodore A Kattchee



Name

Certification No. 99-2557

Expires on 03/10/14

This certification was issued by the Division of Occupational Safety and Health as authorized by Sections 7180 et seq. of the Business and Professions Code.

State of California
Division of Occupational Safety and Health
Certified Site Surveillance Technician

Steven B Rogers



Name

Certification No. 08-4408

Expires on 08/21/14

This certification was issued by the Division of Occupational Safety and Health as authorized by Sections 7180 et seq. of the Business and Professions Code.